BGJMC Briefing Note

surnham Green Traffic Calming Update	Committee /Working Group Cllr Florence
/hy	
esident Concern	
/here lap	
(12m) ¹ /	
ACCE A X	W Iliam Spring Bull's Green
enfordshim)	20230081
THE WAS	12500
Stables	20230082
200	
Stables 123m	
Burnham Green Gub Cottages Burnham	
Green 20220083 Tewin	
Lodge Farm Wood	

BGJMC Briefing Note

When

Results of the 2023 speed and volume surveys below:

Site No: 20230081

	Mean Speed (mph)	85 th Percentile (mph)
Southeastbound	25.72	30.32
Northwestbound	27.95	33.24

Site No: 20230082

	Mean Speed (mph)	85 th Percentile (mph)
Southwestbound	27.37	32.12
Northeastbound	27.58	32.64

Site No: 20230083

	Mean Speed (mph)	85th Percentile (mph)
Southwestbound	27.18	32.57
Northeastbound	25.87	31.45

As all of the above are on a 30mph speed limit road and the mean speed in all survey locations falls below the speed limit, a SID (Speed Indicator Device) is not needed in this location. The current cost of a SID is up to £5,100. This includes 5 years of maintenance. In the sixth year, £1,000 maintenance fee is required for the warranty but covers another 5 years of maintenance.

Hope Merriman (Asst. Highways Manager)